

**DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
ANCHORAGE TERMINAL RADAR APPROACH CONTROL
5200 West International Airport Road
Anchorage, Alaska 99502-1025
www.alaska.faa.gov/ata**

ISSUED: August 24, 2004

EFFECTIVE: September 24, 2004

ANCHORAGE TERMINAL RADAR APPROACH CONTROL LETTER TO AIRMEN NO. 04-05


SUBJECT: VFR Aircraft Conducting Practice Instrument Approaches

CANCELLATION: September 23, 2006

VFR aircraft conducting practice instrument approaches at Anchorage International Airport, Merrill Field Airport and Elmendorf Air Force Base will be provided appropriate IFR separation as described in the Aeronautical Information Manual, paragraph 4-3-21. Controller responsibility for separation begins at the point where the approach clearance becomes effective.

Aircraft requesting practice instrument approaches should contact Anchorage Approach Control on 119.1/363.2 or 118.6/290.5 when approaching from the north and 126.4 or 123.8/257.9 when approaching from the south.

If you have any questions on this procedure please contact us at 271-2700.



John H. Craft
Air Traffic Manager
Anchorage Terminal Radar Approach Control